


## Automatic corner radiusing ( R ) and chamfering ( C )

It is possible to automatically generate a chamfer or radius between two connecting linear moves. Just program the lines to the theoretical intersection point of the two move and put a C or R with the absolute amount of the radius or chamfer needed.



### Format

$$X_n Z_n R_n - Z_n R_n - X_n R_n$$
$$X_n Z_n C_n - Z_n C_n - X_n C_n$$

$X_n Z_n$  The linear move leading to the intersection point of two lines  
 $R_n$  The n is the absolute value of the radius used to blend the two lines  
 $C_n$  The n is the absolute value of the chamfer used to blend the two lines

### RULES

The moves that are connected by the auto chamfer or radius *must be linear moves*. The C or R command will not work with blending arcs or arcs and lines. If you want to blend these use G02 and G03.

The moves do not have to be at right angles

A chamfer created is set back equally from the intersection point of the two lines.

A radius created is made tangential to the two intersecting lines. The direction (CW or CCW) of the radius is determined automatically by the OmniTurn. It looks ahead to the next move.

The n value must be the absolute (+) value

### Running programs using C or R


When you use the automatic corner radius or chamfer commands the OmniTurn creates a number of moves to generate what you want. If you look at the command line while you run a program you will notice lines of code that you did write. In the single block mode you can see arc (G02 or G03)

## Automatic corner radiusing ( R ) and chamfering ( C )

commands. This is normal. When you leave the editor the OmniTurn automatically recreates the new moves. The program is also recreated whenever you change the secondary offset table.

### Example

Note: The example program shown uses more codes than shown yet to this point in the book. M03, M08, G41, Dn and G40 are covered in other sections.



```
G90G72G94F300
M03S2500
M08
T1 (LH turn tool)
X0Z1
Z.05
G95F.001
G41
Z0D1
X.27C.03
Z-.35C.03
X.5R.025
Z-.45
X.54
G00Z1
G40
M30
```

*G72 Program is in diameter mode*  
Turn the spindle on at 2500 rpm  
Turn the coolant on

*Turn on LH cutter compensation*  
*Use the radius value found in D1 for comp*  
*set chamfer amount*  
*set chamfer amount*  
*set radius amount*

*move off the part more than the comp. value*

*turn cutter compensation off*