


OmniTurn



MC2 “Delay Board”:
Mounts on non-component side of MC2 opposite U40.